



www.partyprorents.com

Popcorn Machine Instructions

**NEVER POP CORN IN DRY KETTLE
TURN KETTLE OFF WHEN NOT IN USE**

Operations Instructions

1. Turn Light and Kettle switches "ON" and allow to pre heat 5-7 minutes before first popping
2. Add popcorn oil or seasoning to kettle (use 1/4 to 1/3 oil to corn ratio)
3. Use measuring cup, fill level with raw corn, add salt to taste and pour into kettle
4. Dump all corn from kettle when popping stops

***Machine operates best when plugged in on its own breaker
A 110 outlet is required to operate***